

# C L E A N    --    C A R E

Adviesburo voor reiniging en onderhoud van kunststof-vloeren  
R.M.P. Goovaerts, Beethovensingel 107, NL - 6371 LE Landgraaf.  
tel : +3145 5690068/fax : +3145 5691204/GSM : +316 53936733  
E-mail : info@clean-care.nl

=====

## **cleaning manual for new and (extreme) dirty floors**

### **removing rubber-marks**

In case of rubber marks on the floor, spray them with **ULTRA/ULTRA 60+** as mentioned below

**very important : N E V E R scrub a dry synthetic floor with dry brushes/pads;**

depending on the pollution, wash the floor/part of the floor (only scrubbing), with the machine or foam with the foam-gun from 1:30/1:50 and 1:20 by hand, with **ULTRA : cold water;** use up the chemicals-tank and refill with only **cold water;** check if the chemicals did its work and if not scrub again with the machine and a little water;

**now scrub the floor but with double the waterquantity and aspirate the scrubbing-water;**

**above procedure has to be carried out with the greatest carefulness and without any hurry;**

wash and scrub smooth floors with thick **RED/GREEN 3M** nylonpads and non-smooth floors with a

### **roller-brushes machine**

On **new floors** and depending on the type (**removing 'parafine-layer'**) one cleaning-run as above has to be carried out

**I M P O R T A N T : "always clean the floor first before any activity takes place on the floor"**

### **removal of tyre-/shoe-marks**

**spray ULTRA/ULTRA 60+** on the marks pure or 1:1 and let stay till almost dried; hereafter wash away with a nylonpad/sponge; when many marks they can be scrubbed away with a single-disc hand-machine with a **RED** nylonpad;

**ULTRA-gel 60+** can be used on very dirty floors and for the removal of floor wax, tyre-/shoe-marks, hydraulic-oils etc.

Landgraaf, January 2012.